CREW:	CREW: 61 WORK ORDER TYPE: PM REPAIR			03-96033-48		ISSUE DATE 01/06/11	Page 1 Of 3					
_	nator : KEVIN MILLER	Schedule Date			/07	Date Completed:		Failure Code	:			
Plann		*	: 3									
	ng No : 1SGA-M2063D	Clearance	: Y	ES		Completed By :		Signature	:			
	No/Cat: 1SGAA 1	Tag Request				Aggent od Dvr		O d mm a buuna				
_	,		: Accepted By : : NOT SCHEDULED				signature	:				
Ref N				: No Reading			** Delay Codes Legend **					
101 10	si no : Dasc Reading		• •	. No kedding			W=Whse C=CrSp T=Tag TL=Tool P=Plan					
									aily **			
Step	Job Scope		MN	DY	Safety and Addit	ional Information	Emp No	Date	Hours	Code/Hrs		
						cional Information						
1	BOTH UNITS: INSTALL POWER CIRCUIT TO NEW HOIST B6A LOCATED ON THE BOILER NORTH SIDE ON THE 8TH FLOOR.			1	******	******						
					•	MENTAL REQUIREMENTS:						
					A. ALWAYS WEAR	THE REQUIRED PPE.						
	**********					CARD FOR TERMINATION TO						
	JOB SCOPE:				THE SPARE BREAKE	CRS IN POWER PANEL 127.						
	1. THE HOISTS SHOULD ALREADY BE HANGING				C MIE OPP WITE	NI MODELING OUTD BOILD BRIEF						
	OVER THE HATCH OPENING ON THE BACK SIDE OF THE 8TH FLOOR.				C. IIE OFF WHE	N WORKING OVER FOUR FEET.						
	THE 8TH FLOOR.				ח זוכע האזוייז הא	ESPECIALLY ON THE 10TH				-		
	2. INSTALL A 1" CONDUIT FROM PPL-127 LOCATED ON THE NW CORNER OF THE BOILER 13TH FLOOR TO VERTICAL TRAY AS SHOWN ON THE MARKED UP RACEWAY DRAWING. EXISTING HANGERS CAN BE USED FOR THE ENTIRE RUN.					TRAY WHICH IS COVERED AND						
					OVER NOTHING.	Trail Willell 10 COVERED AND						
					******	******						
					ADDITIONAL INFOR	MATION:						
					A. OBTAIN CON	DUIT AND WIRE WHICH IS						
	3. INSTALL A 1" CONDUIT FROM THE TRAY				STAGED AT THE WA	REHOUSE. OTHER MATERIALS						
	0057 ON THE 8TH FLOOR TO THE HOIST.					CONDUIT JOB ARE LOCATED IN						
	INSTALL STRUT AS NEEDED F	FOR ADEQUATE			THE SHOP BINS.							
	SUPPORT SYSTEM.							-				
	4 DITT > 4/G #102WG FF	AV CARLE EDOM MUD			B. HOISTS ARE	ALREADY HANGING.						
	4. PULL A 4/C #10AWG TR											
	PPL TO THE HOIST. TERMINATE THE CABLE ON BREAKERS 19-21-23 IN THE PPL AS NOTED ON											
	THE ATTACHED MARKED UP ONE-LINE.											
	TERMINATE THE CABLE IN THE HOIST AS							······································				
	NEEDED. NOTE: THE HOIST IS PREWIRED AS 230V BUT APPEARS FROM THE NAMEPLATE THAT IT CAN BE											
	WIRED 460V. CONSULT SUPV WITH ANY						4	* IMPORTANT	NOTICE **			
	QUESTIONS.								YOUR OWN SAFE	TY AND MUST		
							ENSURE THAT	THE REQUIRE	D PPE IS WORN I	FOR EVERY		
	5. ENERGIZE AND TEST ROTATION AND								YOU HAVE ANY QU			
	FUNCTIONS OF THE PENDANT CONTROL.			CONCERNING THE WORK RULES,				ES, SAFETY CODE	ES, OR			

Job Feedback/Historical Notes:



REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

CREW: 61 WORK ORDER TYPE: PM REPAIR 03-96033-48 ISSUE DATE 01/06/11 Page 2 Of 3

Step Job Scope Cont'd MN DY Safety and Additional Information Cont'd Notes Cont'd:

6. INSTALL NEW PANELBOARD DIRECTORIES.

7. RETURN ALL DOCUMENTATION WITH THIS PACKAGE.

CREW: 61 WORK ORDER TYPE: PM REPAIR 03-96033-48 ISSUE DATE 01/06/11 Page 3 Of 3

**	Work	Order	Darte	T.ic+	*

:	Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
				~				
1	06591	FUSE, 003.00 AMP	S 411035	01/29/08	EA	1	0	1
2	41712	DETECTOR, LEAK	S 411035	01/29/08	ĒΑ	1	0	1
3	58171	CONDUIT, FLEXIBLE	S 409164*	01/10/08	FT	4	0	4
4	58396	CONDUIT, RIGID	S 389572	06/04/07	PC	12	0	12
5	80842	WIRE (ELECT), TRAY CABLE	S 389572	06/04/07	FT	600	0	600